	Work for Property Loc Property is: Single Far		Duplex	☐ Other ☐		
Date:	10/22/2014	illy 🕒	Duplex	□ Other □		-
	•		ofoty iccuo	s. The City of Milwaukoo	the Redevelopment Authority and their re	procentatives
ake no respo	onsibility for problems discovered	after the ins	spection da	ate, or for omissions throug	the Redevelopment Authority, and their reght error or oversight. The list does not ned	•
vork required	d by private lenders, insurance co	mpanies, or	by the Fed	deral Block Grant or HOM	E programs.	
Exterior	Condition Report					
_ocation	Required Work			Note/Comments		Cost
Site	Landscaping	n/a ✓	Yes 🗌	Self Help	\$	
	Steps/Handrails	n/a ✓	Yes 🗌		\$	
	Service walks	n/a ✓	Yes 🗌		\$	
	Fencing	n/a ✓	Yes 🗌		\$	
	Parking	n/a	Yes 🗸	incl driveway	\$	5,000.00
	Retaining walls	n/a ✓	Yes 🗌		\$	
	Other	n/a 🗌	Yes $\square$		\$	
	Other	n/a 🗌	Yes 🗌		\$	
Garage		, 5				
	Singles: repair	n/a 📙	Yes 📙		\$	
	Shingles: Roof over existing	n/a	Yes		\$	
	Shingles:Tear off & re-roof	n/a	Yes 🗌		\$	
	Gutters/downspouts	n/a	Yes 🗌		\$	
	Flashing	n/a	Yes 🗌		\$	
	Eaves	n/a	Yes 🗌		\$	
	Siding	n/a	Yes 🗌		\$	
	Doors	n/a 🗌	Yes 🗌		\$	
	Windows	n/a	Yes 🗌		\$	
	Slab	n/a	Yes 🗌		\$	
	Paint	n/a 🗌	Yes 🗌		\$	
	Electrical	n/a	Yes 🗌		\$	
	Other	n/a 🗌	Yes 🗌		\$	
Porches	Roof	n/a ☑	Yes 🗌		\$	
	Deck-upper	n/a $\square$	Yes ✓		\$	4,200.00
	Decklower	n/a $\square$	Yes ✓	front & south porche		3,540.00
				Home & South porch	\$	3,340.00
	Steps/handrails		Yes			
	Ceiling	n/a ☑	Yes 🗌		\$	
	Guardrails	n/a ✓	Yes 🗌		\$	
	Structural	n/a ✓	Yes 🗌		\$	
	Paint	n/a	Yes 🗸		\$	1,000.00

n/a ☐ Yes ☐

Other

\$

## House

Chimney	n/a ☐ Yes ☑	\$	450.00
Shingles: repair	n/a ✓ Yes 🗌	\$	
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$	
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$	8,720.00
Gutters/downspouts	n/a 🗸 Yes 🗌	\$	
Flashing	n/a 🗸 Yes 🗌	\$	
Eaves	n/a 🗌 Yes 🗸 fascia & soffit	\$	600.00
Siding	n/a 🗌 Yes 🗸	\$	300.00
Storm Doors	n/a 🗸 Yes 🗌	\$	
Prime ("main") Doors	n/a 🗌 Yes 🗸	\$	1,050.00
Storm Windows	n/a ✓ Yes 🗌	\$	
Prime ("main") Windows	n/a 🗌 Yes 🗸	\$	
Paint	n/a 🗌 Yes 🗸	\$	2,400.00
Foundation	n/a ✓ Yes 🗌	\$	
Electrical	n/a Yes v new service	\$	2,000.00
Other	n/a 🗌 Yes 🗸 basement windows (2	2 w/screens) \$	1,200.00
Other	n/a  Yes  rear enclosed porch	\$	5,000.00
Other	n/a 🗌 Yes 🗌	\$	
Other	n/a  Yes	\$	

Exterior: Estimated Cost:\* \$ 35,460.00
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	Ondition Report Unit: Entire unit (single family) Upper unit of duplex	✓ □			Lower unit of duplex  Other	
Mechanical Heating	Required Work					
	Repair/replace boiler	n/a ✓	Yes	s 🗌		\$ 
	Repair radiation	n/a Ū	Yes	s 🗌		\$ 
	Repair/replace furnace	n/a	Yes	s 🗸		\$ 3,080.00
	Repair ductwork	n/a	Yes	s 🗸		\$ 600.00
	Replace thermostat	n/a	Yes	s 🗸		\$ 100.00
	Repair/replace grilles	n/a ☑	Yes	s 🗌		\$ 
Electrical	Other	n/a	Yes	s 🗸	permit	\$ 85.00
Electrical	Repair/replace receptacles	n/a	Yes	3 🗸		\$ 800.00
	Repair/replace switches	n/a	Yes	s 🗸		\$ 800.00
	Repair/replace fixtures	n/a	Yes	s 🗸		\$ 800.00
	Install outlets and circuits	n/a ☑	Yes	s 🗌		\$ 
	Install outlets and circuits	n/a ✓	Yes	s 🗌		\$
	Install outlets and circuits	n/a ☑	Yes	s 🗌		\$
	Install outlets and circuits	n/a ✓	Yes	s 🗌		\$
	Upgrade service	n/a	Yes	s 🗸		\$ 1,749.00
	Other	n/a 🗌	Yes	s 🗸	permit	\$ 85.00
Diversities	Other	n/a 🗌	Yes	s 🗌		\$
Plumbing	Repair/replace kitchen sink	n/a	Yes	s 🗌		\$
	Repair/replace kitchen sink fauce	n/a	Yes	s 🗌		\$ 
	Repair/replace tub	n/a ✓	Yes	s 🗌		\$
	Repair/replace tub faucet	n/a	Yes	s 🗸		\$ 392.00
	Repair/replace toilet	n/a	Yes	s 🗸		\$ 298.00
	Repair/replace lavatory	n/a	Yes	s 🗌		\$ 
	Repair/replace lavatory faucet	n/a [	Yes	3 🗌		\$ 
	Repair/replace wash tub	n/a ✓	Yes	s 🗌		\$
	Repair/replace wash tub faucet	n/a ☑	Yes	s 🗌		\$
	Unclog piping:	n/a ✓	Yes	s 🗌		\$ 
	Repair drain/waste/vent piping	n/a	Yes	s 🗸		\$ 440.00
	Repair water piping	n/a	Yes	s 🗸		\$ 525.00
	Repair/replace water heater	n/a	Yes	s 🗸		\$ 1,300.00
	Other	n/a	Yes	s 🗸	complete kitchen	\$ 1,455.00

n/a ☐ Yes ☑ **permit** 

85.00

Other

						Total Exterior and Interior Cost:*	\$	58,021.00
						Interior: Estimated Cost:	\$	22,561.00
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a	<u>Ц</u>	Yes	<u> </u>		\$	
	-	n/a		Yes			\$	
Other	. topan dorodiro				<u> </u>			2,000.00
Floors	Repair defective	n/a	П	Yes	<b>7</b>		\$	2,800.00
Stairs	Repair defective	n/a		Yes	<b>V</b>	to basement	\$	864.00
	Repair/replace defective	n/a		Yes	<b>√</b>	Self Help	\$	248.00
Handrails	Install smoke/CO alarm: 2nd flr.	n/a		Yes	<b>V</b>	Self Help	\$	110.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>V</b>	Self Help	\$	110.00
i ne Salety	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>V</b>	Self Help	\$	55.00
Fire Safety	Trepail Of Tepl. & defective	11/a		162	Ľ		φ	1,000.00
Paint	Repair or repl. @ defective	n/a		Yes	<b>7</b>		\$	1,600.00
•	Repair or repl. @ defective	n/a		Yes	1		\$	3,200.00
Walls/Ceilin	Repair or repl. locks/latches	n/a		Yes	<b>✓</b>	Self Help	\$	220.00
	Repair or replace doors	n/a		Yes	✓ _		\$	760.00
Doors	Repair or replace sasir	II/a		168	Ш		Φ	
	Repair or replace sash		<u> </u>	Yes			\$	
Windows	Replace broken glass	n/a	[J]	Yes			\$	

Inspected by: Tom Frank Date: 10/21/14

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

 $<sup>\</sup>ensuremath{^{\star}}\xspace$  average contracted cost. Actual costs may vary. Self help will reduce the amount.